

# FACILITY CONDITION ASSESSMENT

*Prepared for*

DLR Group  
1650 Spruce Street, Suite 300  
Riverside, California 92507  
Kevin Fleming



FACILITY CONDITION ASSESSMENT  
OF  
CIRCLE VIEW ELEMENTARY  
6261 HOOKER LANE  
HUNTINGTON BEACH, CALIFORNIA 92647

## PREPARED BY:

EMG  
10461 Mill Run Circle, Suite 1100  
Owings Mills, Maryland 21117  
800.733.0660  
[www.emgcorp.com](http://www.emgcorp.com)

## EMG CONTACT:

Mark Surdam  
Program Manager  
800.733.0660 x6251  
[msurdam@emgcorp.com](mailto:msurdam@emgcorp.com)

## EMG PROJECT #:

119317.16R000-001.017

## DATE OF REPORT:

June 6, 2016

## ONSITE DATE:

May 4, 2016



engineering | environmental | capital planning | project management

**Immediate Repairs Report**  
**Circle View Elementary**  
**6/6/2016**


Report Section	ID	Cost Description	Quantity	Unit	Unit Cost	Subtotal	Deficiency Repair Estimate *
5.2	437752	Concrete Sidewalk, Repair	200	SF	\$28.94	\$5,789	<b>\$5,789</b>
6.6	441039	Exterior Door, Steel, Refinish	27	EA	\$69.94	\$1,888	<b>\$1,888</b>
7.1	436915	Condensing Unit/Heat Pump, Split System, 4 Ton, Replace	1	EA	\$4,619.82	\$4,620	<b>\$4,620</b>
7.1	436914	Package Unit, 3.5 Ton, Replace	1	EA	\$10,226.65	\$10,227	<b>\$10,227</b>
7.1	436673	Package Unit, 21 to 25 Ton, Replace	5	EA	\$44,377.70	\$221,889	<b>\$221,889</b>
7.1	436901	Heat Pump, 3.5 to 5 Ton, Replace	1	EA	\$8,928.22	\$8,928	<b>\$8,928</b>
7.1	436911	Heat Pump, 3.5 to 5 Ton, Replace	3	EA	\$8,928.22	\$26,785	<b>\$26,785</b>
7.1	436674	Building Automation System (HVAC Controls), Upgrade	44000	SF	\$3.85	\$169,400	<b>\$169,400</b>
8.1	439275	Interior Ceiling Finish, Acoustical Tile (ACT), Repair	44000	SF	\$3.10	\$136,488	<b>\$136,488</b>
<b>Immediate Repairs Total</b>							<b>\$586,013</b>

\* Location Factor (1.0) included in totals.

Replacement Reserves Report

Circle View Elementary



6/6/2016

Report Section	ID	Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	Unit	Unit Cost	Subtotal	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	Deficiency Repair Estimate
5.2	437752	G2031 Concrete Sidewalk, Repair	0	0	0	200	SF	\$28.94	\$5,789	\$5,789																				\$5,789
6.3	443228	B3011 Roof, Modified Bituminous, Replace	20	15	5	13604	SF	\$9.01	\$122,508						\$122,508															\$122,508
6.6	441039	B2032 Exterior Door, Steel, Refinish	10	10	0	27	EA	\$69.94	\$1,888	\$1,888									\$1,888											\$3,777
7.1	436676	D3032 Condensing Unit/Heat Pump, Split System, 4 Ton, Replace	15	3	12	1	EA	\$4,619.82	\$4,620												\$4,620									\$4,620
7.1	436915	D3032 Condensing Unit/Heat Pump, Split System, 4 Ton, Replace	15	15	0	1	EA	\$4,619.82	\$4,620	\$4,620															\$4,620					\$9,240
7.1	436675	D3032 Condensing Unit/Heat Pump, Split System, 5 Ton, Replace	15	3	12	2	EA	\$6,439.81	\$12,880												\$12,880									\$12,880
7.1	436914	D3052 Package Unit, 3.5 Ton, Replace	15	15	0	1	EA	\$10,226.65	\$10,227	\$10,227															\$10,227					\$20,453
7.1	436905	D3052 Heat Pump, 3.5 to 5 Ton, Replace	15	5	10	1	EA	\$8,928.22	\$8,928										\$8,928											\$8,928
7.1	436673	D3052 Package Unit, 21 to 25 Ton, Replace	15	15	0	5	EA	\$44,377.70	\$221,889	\$221,889															\$221,889					\$443,777
7.1	436901	D3052 Heat Pump, 3.5 to 5 Ton, Replace	15	15	0	1	EA	\$8,928.22	\$8,928	\$8,928															\$8,928					\$17,856
7.1	436911	D3052 Heat Pump, 3.5 to 5 Ton, Replace	15	15	0	3	EA	\$8,928.22	\$26,785	\$26,785															\$26,785					\$53,569
7.1	436674	D3068 Building Automation System (HVAC Controls), Upgrade	20	0	* 20	44000	SF	\$3.85	\$169,400	\$169,400																				\$169,400
7.4	436917	D5019 Electrical System, School, Upgrade	40	35	5	44955	SF	\$20.78	\$933,940						\$933,940															\$933,940
8.1	439275	C3032 Interior Ceiling Finish, Acoustical Tile (ACT), Repair	0	0	0	44000	SF	\$3.10	\$136,488	\$136,488																				\$136,488
8.3	440231	E1093 Refrigerator, Commercial Kitchen, Replace	15	8	7	2	EA	\$1,406.90	\$2,814							\$2,814														\$2,814
8.3	440230	E1093 Freezer/Cooler, Commercial, Walk-In, Replace	15	8	7	1	EA	\$22,317.14	\$22,317							\$22,317														\$22,317
8.3	440228	E1093 Food Warmer, Replace	15	8	7	1	EA	\$1,551.91	\$1,552							\$1,552														\$1,552
Totals, Unescalated										\$586,013	\$0	\$0	\$0	\$0	\$1,056,448	\$0	\$26,683	\$0	\$0	\$10,817	\$0	\$17,499	\$0	\$0	\$272,448	\$0	\$0	\$0	\$0	\$1,969,908
Location Factor (1.00)										\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Totals, Escalated (3.0% inflation, compounded annually)										\$586,013	\$0	\$0	\$0	\$0	\$1,224,713	\$0	\$32,817	\$0	\$0	\$14,537	\$0	\$24,950	\$0	\$0	\$424,465	\$0	\$0	\$0	\$0	\$2,307,494

## TABLE OF CONTENTS

<b>1. Executive Summary .....</b>	<b>1</b>
1.1. Property Information and General Physical Condition .....	1
1.2. Facility Condition Index (FCI) .....	2
1.3. Special Issues and Follow-Up Recommendations .....	3
1.4. Opinions of Probable Cost .....	3
1.4.1. Methodology .....	4
1.4.2. Immediate Repairs .....	4
1.4.3. Replacement Reserves .....	4
<b>2. Purpose and Scope .....</b>	<b>5</b>
2.1. Purpose .....	5
2.2. Scope .....	6
2.3. Personnel Interviewed .....	7
2.4. Documentation Reviewed .....	7
2.5. Pre-Survey Questionnaire .....	8
2.6. Weather Conditions .....	8
<b>3. Accessibility &amp; Property Research .....</b>	<b>9</b>
3.1. ADA Accessibility .....	9
3.2. Municipal Information, Flood Zone and Seismic Zone .....	9
<b>4. Existing Building Assessment .....</b>	<b>10</b>
4.1. Space Types .....	10
4.2. Inaccessible Areas or Key Spaces Not Observed .....	10
<b>5. Site Improvements .....</b>	<b>11</b>
5.1. Utilities .....	11
5.2. Parking, Paving, and Sidewalks .....	11
5.3. Drainage Systems and Erosion Control .....	12
5.4. Topography and Landscaping .....	13
5.5. General Site Improvements .....	13
<b>6. Building Architectural and Structural Systems .....</b>	<b>15</b>
6.1. Foundations .....	15
6.2. Superstructure .....	15
6.3. Roofing .....	15
6.4. Exterior Walls .....	17
6.5. Exterior and Interior Stairs .....	17
6.6. Exterior Windows and Doors .....	17
6.7. Patio, Terrace, and Balcony .....	18
<b>7. Building Mechanical and Plumbing Systems .....</b>	<b>19</b>
7.1. Building Heating, Ventilating, and Air Conditioning (HVAC) .....	19
7.2. Building Plumbing and Domestic Hot Water .....	19
7.3. Building Gas Distribution .....	20
7.4. Building Electrical .....	20
7.5. Building Elevators and Conveying Systems .....	21
7.6. Fire Protection and Security Systems .....	21
<b>8. Interior Spaces .....</b>	<b>23</b>
8.1. Interior Finishes .....	23
8.2. Furniture, Fixtures and Equipment (FF&E) .....	24
8.3. Commercial Kitchen equipment .....	24
<b>9. Other Structures .....</b>	<b>25</b>
<b>Certification .....</b>	<b>26</b>
<b>10. Appendices .....</b>	<b>27</b>



## FACILITY CONDITION ASSESSMENT

CIRCLE VIEW ELEMENTARY  
6261 HOOKER DRIVE  
HUNTINGTON BEACH, CALIFORNIA 92647

EMG PROJECT NO: 119317.16R000-001.017

# 1. EXECUTIVE SUMMARY

## 1.1. PROPERTY INFORMATION AND GENERAL PHYSICAL CONDITION

The property information is summarized in the table below. More detailed descriptions may be found in the various sections of the report and in the Appendices.

PROPERTY INFORMATION	
Address:	6261 Hooker Drive, Huntington Beach, CA 92647
Year Constructed/Renovated:	1965, Phase I / 1997/2010 Portables /, Added Rest Room Buildings 2015
Current Occupants:	Students
Management Point of Contact:	Ocean View School District Craig Sample, Maintenance & Operations Supervisor 714.847.7083 phone 714.847.3445 cell csample@ovsd.org
Property Type:	Elementary School
Site Area:	12.17 acres
Building Area:	53,275 SF
Number of Buildings:	5 Classroom Buildings (Pods), 1 Admin, 1 MPR – 6 Portables
Number of Stories:	1
Parking Type and Number of Spaces:	37 spaces in open lots, 2 Accessible Car, 1 Accessible Van
Building Construction:	Wood framed and wood panel roof
Roof Construction:	Flat roofs with built-up membrane
Exterior Finishes:	Brick Veneer
Heating, Ventilation and Air Conditioning:	Roof Top Package with Zone Dampers- Classrooms, Split units in Admin and MPR Heat pump – Portables
Fire and Life/Safety:	Smoke detectors, alarms, strobes, extinguishers, pull stations, alarm panel, and exit signs
Dates of Visit:	05/04/2016
On-Site Point of Contact (POC):	Noah Valadez
Assessment and Report Prepared by:	Steve Novotny
Reviewed by:	George Luce Technical Report Reviewer gluce@emgcorp.com 800.733.0660 x6261

SYSTEMIC CONDITION SUMMARY			
Site	Excellent	HVAC	Fair

## FACILITY CONDITION ASSESSMENT

CIRCLE VIEW ELEMENTARY  
6261 HOOKER DRIVE  
HUNTINGTON BEACH, CALIFORNIA 92647

EMG PROJECT NO: 119317.16R000-001.017

SYSTEMIC CONDITION SUMMARY			
Structure	Excellent	Plumbing	Good
Roof	Good	Electrical	Good
Vertical Envelope	Excellent	Elevators	--
Interiors	Fair	Fire	Excellent

The following bullet points highlight the most significant short term and modernization recommendations:

- Replacement of rooftop package units
- DDC HVAC balancing and control system upgrade
- Modernization of electrical system, replace original 1965 Switch Gear Enclosures , branch reportedly upgraded in 2002/4
- Significant ADA accessibility upgrades – based on previous ADA study and upgrades scheduled for Aug 2016
- Repair Parking Lot


Generally, the property appears to have been constructed within industry standards in force at the time of construction. The property appears to have been well maintained in recent years and is in excellent overall condition.

According to property management personnel, the property has had an active capital improvement expenditure program over the past three years, primarily consisting of new carpeting, exterior painting, asphalt pavement seal coating, and roof finish replacement. Supporting documentation was not provided in support of these claims but some of the work is evident.

## 1.2. FACILITY CONDITION INDEX (FCI)

### FCI Analysis: Circle View Elementary

▲ Replacement Value: \$ 9,494,000; Inflation rate: 3.0%



## FACILITY CONDITION ASSESSMENT

CIRCLE VIEW ELEMENTARY  
6261 HOOKER DRIVE  
HUNTINGTON BEACH, CALIFORNIA 92647

EMG PROJECT NO: 119317.16R000-001.017

One of the major goals of the FCA is to calculate the FCI, which gives an indication of a building's overall condition. Two FCI ratios are calculated and presented, the Current Year and Ten-Year. The Current Year FCI is the ratio of Immediate Repair Costs to the building's Current Replacement Value. Similarly, the Ten-Year FCI is the ratio of anticipated Capital Reserve Needs over the next ten years to the Current Replacement Value.

FCI CONDITION RATING	DEFINITION	PERCENTAGE VALUE
Good	In new or well-maintained condition, with no visual evidence of wear, soiling or other deficiencies.	0% to 5%
Fair	Subjected to wear and soiling but is still in a serviceable and functioning condition.	> than 5% to 10%
Poor	Subjected to hard or long-term wear. Nearing the end of its useful or serviceable life.	> than 10% to 60%
Very Poor	Has reached the end of its useful or serviceable life. Renewal is now necessary.	> than 60%

The graphs above and tables below represent summary-level findings for the FCA. The deficiencies identified in this assessment can be combined with potential new construction requirements to develop an overall strategy that can serve as the basis for a portfolio-wide capital improvement funding strategy. Key findings from the assessment include:

KEY FINDING	METRIC	
Current Year Facility Condition Index (FCI) $FCI = (IR)/(CRV)$	6.2%	Fair
10-Year Facility Condition Index (FCI) $FCI = (RR)/(CRV)$	11.7%	Poor
Current Replacement Value (CRV)	\$9,494,000	
Year 0 (Current Year) - Immediate Repairs (IR)	\$586,013	
Years 1-10 – Replacement Reserves (RR)	\$1,115,509	
<b>TOTAL Capital Needs</b>	<b>\$1,701,522</b>	

The major issues contributing to the Immediate Repair Costs and the Current Year FCI ratio are summarized below:

- Replace Rooftop Package Units
- Add Digital Control (DDC) System
- Replace Heat Pumps on Portables

Further detail on the specific costs that make up the Immediate Repair Costs can be found in the cost tables in the appendices.

### 1.3. SPECIAL ISSUES AND FOLLOW-UP RECOMMENDATIONS

As part of the FCA, a limited assessment of accessible areas of the building(s) was performed to determine the presence of suspected fungal growth, conditions conducive to such growth, and/or evidence of moisture. Property personnel were interviewed concerning any known or suspected fungal growth, elevated relative humidity, water intrusion, or mildew-like odors. Sampling is not a part of this assessment.

### 1.4. OPINIONS OF PROBABLE COST

Cost estimates are attached at the front of this report (following the cover page).

These estimates are based on Invoice or Bid Document/s provided either by the Owner/facility and construction costs developed by construction resources such as *R.S. Means* and *Marshall & Swift*, EMG's experience with past costs for similar properties, city cost indexes, and assumptions regarding future economic conditions.

Opinions of probable costs should only be construed as preliminary, order of magnitude budgets. Actual costs most probably will vary from the consultant's opinions of probable costs depending on such matters as type and design of suggested remedy, quality of materials and installation, manufacturer and type of equipment or system selected, field conditions, whether a physical deficiency is repaired or replaced in whole, phasing of the work (if applicable), quality of contractor, quality of project management exercised, market conditions, and whether competitive pricing is solicited, etc. ASTM E2018-15 recognizes that certain opinions of probable costs cannot be developed within the scope of this guide without further study. Opinions of probable cost for further study should be included in the FCA.

---

### 1.4.1. METHODOLOGY

Based upon site observations, research, and judgment, along with referencing Expected Useful Life (EUL) tables from various industry sources, EMG opines as to when a system or component will most probably necessitate replacement. Accurate historical replacement records, if provided, are typically the best source of information. Exposure to the elements, initial quality and installation, extent of use, the quality and amount of preventive maintenance exercised, etc., are all factors that impact the effective age of a system or component. As a result, a system or component may have an effective age that is greater or less than its actual chronological age. The Remaining Useful Life (RUL) of a component or system equals the EUL less its effective age. Projections of Remaining Useful Life (RUL) are based on continued use of the Property similar to the reported past use. Significant changes in occupants and/or usage may affect the service life of some systems or components.

Where quantities could not be derived from an actual take-off, lump sum costs or allowances are used. Estimated costs are based on professional judgment and the probable or actual extent of the observed defect, inclusive of the cost to design, procure, construct and manage the corrections.

---

### 1.4.2. IMMEDIATE REPAIRS

Immediate repairs are opinions of probable costs that require immediate action as a result of: (1) material existing or potential unsafe conditions, (2) material building or fire code violations, or (3) conditions that, if not addressed, have the potential to result in, or contribute to, critical element or system failure within one year or will most probably result in a significant escalation of its remedial cost.

---

### 1.4.3. REPLACEMENT RESERVES

Replacement Reserves are for recurring probable expenditures, which are not classified as operation or maintenance expenses. The replacement reserves should be budgeted for in advance on an annual basis. Replacement Reserves are reasonably predictable both in terms of frequency and cost. However, Replacement Reserves may also include components or systems that have an indeterminable life but, nonetheless, have a potential for failure within an estimated time period.

Replacement Reserves exclude systems or components that are estimated to expire after the reserve term and are not considered material to the structural and mechanical integrity of the subject property. Furthermore, systems and components that are not deemed to have a material effect on the use of the Property are also excluded. Costs that are caused by acts of God, accidents, or other occurrences that are typically covered by insurance, rather than reserved for, are also excluded.

Replacement costs are solicited from ownership/property management, EMG's discussions with service companies, manufacturers' representatives, and previous experience in preparing such schedules for other similar facilities. Costs for work performed by the ownership's or property management's maintenance staff are also considered.

EMG's reserve methodology involves identification and quantification of those systems or components requiring capital reserve funds within the assessment period. The assessment period is defined as the effective age plus the reserve term. Additional information concerning system's or component's respective replacement costs (in today's dollars), typical expected useful lives, and remaining useful lives were estimated so that a funding schedule could be prepared. The Replacement Reserves Schedule presupposes that all required remedial work has been performed or that monies for remediation have been budgeted for items defined in the Immediate Repair Cost Estimate.

## 2. PURPOSE AND SCOPE

### 2.1. PURPOSE

EMG was retained by the client to render an opinion as to the Property's current general physical condition on the day of the site visit.

Based on the observations, interviews and document review outlined below, this report identifies significant deferred maintenance issues, existing deficiencies, which affect the Property's use. Opinions are rendered as to its structural integrity, building system condition, and the Property's overall condition. The report also notes building systems or components that have realized or exceeded their typical expected useful lives.

#### FORMAT OF THE BODY OF THE REPORT:

Throughout sections 5 through 8 of this report, each report section will typically contain three subsections organized in the following sequence:

- A descriptive table (and/or narrative), which identifies the components assessed, their condition, and other key data points.
- A simple bulleted list of Anticipated Lifecycle Replacements, which lists components and assets typically in Excellent, Good, or Fair condition at the time of the assessment but that will require replacement or some other attention once aged past their estimated useful life. These listed components are typically included in the associated inventory database with costs identified and budgeted beyond the first several years.
- A bulleted cluster of Actions/Comments, which include more detailed narratives describing deficiencies, recommended repairs, and short term replacements. The assets and components associated with these bullets are/were typically problematic and in Poor or Failed condition at the time of the assessment, with corresponding costs included within the first few years.

#### CONDITIONS:

The physical condition of building systems and related components are typically defined as being in one of five conditions: Excellent, Good, Fair, Poor, Failed or a combination thereof. For the purposes of this report, the following definitions are used:

Excellent	=	New or very close to new; component or system typically has been installed within the past year, sound and performing its function. Eventual repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service.
Good	=	Satisfactory as-is. Component or system is sound and performing its function, typically within the first third of its lifecycle. However, it may show minor signs of normal wear and tear. Repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service.
Fair	=	Showing signs of wear and use but still satisfactory as-is, typically near the median of its estimated useful life. Component or system is performing adequately at this time but may exhibit some signs of wear, deferred maintenance, or evidence of previous repairs. Repair or replacement will be required due to the component or system's condition and/or its estimated remaining useful life.
Poor	=	Component or system is significantly aged, flawed, functioning intermittently or unreliably; displays obvious signs of deferred maintenance; shows evidence of previous repair or workmanship not in compliance with commonly accepted standards; has become obsolete; or exhibits an inherent deficiency. The present condition could contribute to or cause the deterioration of contiguous elements or systems. Either full component replacement is needed or repairs are required to restore to good condition, prevent premature failure, and/or prolong useful life.
Failed	=	Component or system has ceased functioning or performing as intended. Replacement, repair, or other significant corrective action is recommended or required.
Not Applicable	=	Assigning a condition does not apply or make logical sense, most commonly due to the item in question not being present.

## FACILITY CONDITION ASSESSMENT

CIRCLE VIEW ELEMENTARY  
6261 HOOKER DRIVE  
HUNTINGTON BEACH, CALIFORNIA 92647

EMG PROJECT NO: 119317.16R000-001.017

### PLAN TYPES:

Each line item in the cost database is assigned a Plan Type, which is the primary reason or rationale for the recommended replacement, repair, or other corrective action. This is the “why” part of the equation. A cost or line item may commonly have more than one applicable Plan Type; however, only one Plan Type will be assigned based on the “best” fit, typically the one with the greatest significance. The following Plan Types are listed in general weighted order of importance:

Safety	=	An observed or reported unsafe condition that if left unaddressed could result in an injury; a system or component that presents a potential liability risk.
Performance/Integrity	=	Component or system has failed, is almost failing, performs unreliably, does not perform as intended, and/or poses a risk to overall system stability.
Accessibility	=	Does not meet ADA, CBC and/or other handicap accessibility requirements.
Environmental	=	Improvements to air or water quality, including removal of hazardous materials from the building or site.
Modernization/Adaptation	=	Conditions, systems, or spaces that need to be upgraded in appearance or function to meet current standards, facility usage, or client/occupant needs.
Lifecycle/Renewal	=	Any component or system in which future repair or replacement is anticipated beyond the next several years and/or is of minimal substantial early-term consequence.

### PRIORITIZATION SCHEME:

One of EMG’s data-sorting exercises and deliverables of fundamental value is to evaluate and rank the recommendations and needs of the facility via a logical and well-developed prioritization scheme. The factors under consideration and built into the evaluation criteria include Plan Type (the “why”), Uniformat/building component type or system (the “what”), and condition/RUL (the “when”). The facility type or importance is also factored into the overall portfolio if relevant information is provided and applicable. EMG utilizes the following prioritization scheme:

Priority 1	=	<b>Immediate/Critical Items:</b> Require immediate action to either (a) correct a safety hazard or (b) address the most important building performance or integrity issues or failures.
Priority 2	=	<b>Potentially Critical Items:</b> Include (a) those safety/liability, component performance or building integrity issues of slightly less importance not captured in Priority 1 and/or (b) issues that if left unchecked could escalate into Immediate/Critical items. Accessibility and ‘stabilized’ environmental issues are also typically included in this subset.
Priority 3	=	<b>Necessary/Recommended Items:</b> Items of concern that generally either require attention or are suggested as improvements within the near term to: (a) improve usability, marketability, or efficiency; (b) reduce operational costs; (c) prevent or mitigate disruptions to normal operations; (d) modernize the facility; (e) adapt the facility to better meet occupant needs; and/or (f) should be addressed when the facility undergoes a significant renovation.
Priority 4	=	<b>Anticipated Lifecycle Replacements:</b> Renewal items which are generally associated with building components performing acceptably at the present time but will likely require replacement or other future attention within the timeframe under consideration.

## 2.2. SCOPE

The standard scope of the Facility Condition Assessment includes the following:

- Visit the Property to evaluate the general condition of the building and site improvements, review available construction documents in order to familiarize ourselves with, and be able to comment on, the in-place construction systems, life safety, mechanical, electrical, and plumbing systems, and the general built environment.
- Identify those components that are exhibiting deferred maintenance issues and provide cost estimates for Immediate Costs and Replacement Reserves based on observed conditions, maintenance history and industry standard useful life estimates. This will include the review of documented capital improvements completed within the last five-year period and work currently contracted for, if applicable.
- Provide a full description of the Property with descriptions of in-place systems and commentary on observed conditions.

## FACILITY CONDITION ASSESSMENT

CIRCLE VIEW ELEMENTARY  
6261 HOOKER DRIVE  
HUNTINGTON BEACH, CALIFORNIA 92647

EMG PROJECT NO: 119317.16R000-001.017

- Provide a general statement of the Subject property's compliance with the Americans with Disability Act (ADA). Compliance with Title 24 California Building Code, Chapter 11B and other California Building Code chapters referenced in Chapter 11B, was not surveyed. This report does not constitute a full accessibility survey, but identifies exposure to selected ADA accessibility issues and the need for further accessibility review.
- Perform a limited assessment of accessible areas of the building(s) for the presence of fungal growth, conditions conducive to fungal growth, and/or evidence of moisture. EMG will also interview Project personnel regarding the presence of any known or suspected fungus, elevated relative humidity, water intrusion, or mildew-like odors. Potentially affected areas will be photographed. Sampling will not be considered in routine assessments.
- List the current utility service providers.
- Review maintenance records and procedures with the in-place maintenance personnel.
- Observe a representative sample of the interior spaces/units, including vacant spaces/units, in order to gain a clear understanding of the property's overall condition. Other areas to be observed include the exterior of the property, the roofs, interior common areas, and the significant mechanical, electrical and elevator equipment rooms.
- Provide recommendations for additional studies, if required, with related budgetary information.
- Provide an Executive Summary at the beginning of this report.

### 2.3. PERSONNEL INTERVIEWED

The management and maintenance staff, building engineers, and some key contractors were interviewed for specific information relating to the physical property, available maintenance procedures, historical performance of key building systems and components, available drawings and other documentation.

NAME AND TITLE	ORGANIZATION	PHONE NUMBER
Craig Sample Maintenance and Operations Supervisor	Ocean View School District	714.847.7083
Noah Valadez Building Maintenance Lead	Ocean View School District	714.349.1882
Mike Hoeker HVAC Maintenance Lead	Ocean View School District	714.642.3258

The FCA was performed with the assistance of Noah Valadez and Mike Hoeker, Ocean View School District, the onsite Point of Contact (POC), who was cooperative and provided information that appeared to be accurate based upon subsequent site observations. The onsite contact is completely knowledgeable about the subject property and answered most questions posed during the interview process. The POC's management involvement at the property has been for the past 25 years.

### 2.4. DOCUMENTATION REVIEWED

Prior to the FCA, relevant documentation was requested that could aid in the knowledge of the subject property's physical improvements, extent and type of use, and/or assist in identifying material discrepancies between reported information and observed conditions. The review of submitted documents does not include comment on the accuracy of such documents or their preparation, methodology, or protocol. The Documentation Request Form is provided in Appendix E.

Although Appendix E provides a summary of the documents requested or obtained, the following list provides more specific details about some of the documents that were reviewed or obtained during the site visit.

- Modernization construction documents by BCA Architects, dated 2/2/2009.
- Summary of recent capital improvements.



## FACILITY CONDITION ASSESSMENT

CIRCLE VIEW ELEMENTARY  
6261 HOOKER DRIVE  
HUNTINGTON BEACH, CALIFORNIA 92647

EMG PROJECT NO: 119317.16R000-001.017

### 2.5. PRE-SURVEY QUESTIONNAIRE

A Pre-Survey Questionnaire was sent to the Client's representative prior to the site visit. The questionnaire is included in Appendix E. Information obtained from the questionnaire has been used in preparation of this report.

### 2.6. WEATHER CONDITIONS

On the day of the site visit, May 3, 2016 the weather was clear, with temperatures in the 60s (°F) and light winds.

## 3. ACCESSIBILITY & PROPERTY RESEARCH

---

### 3.1 ADA ACCESSIBILITY

A complete ADA study was performed in 2015 with noted deficiencies that will be corrected in august 2016.

### 3.2 MUNICIPAL INFORMATION, FLOOD ZONE AND SEISMIC ZONE

According to the California Division of State Architect (DSA), there are no outstanding building code violations on file. The DSA does not have an annual inspection program. They only inspect new construction, work that requires DSA approval, and citizen complaints.

According to the Huntington Beach Fire Department, there are no outstanding fire code violations on file. The Fire Department inspects the property on an annual basis.

According to the Flood Insurance Rate Map, 06059C0232J, published by the Federal Emergency Management Agency (FEMA) and dated December 3, 2009, the property is located in Zone X, defined as an area outside the 500-year flood plain with less than 0.2% annual probability of flooding. Annual Probability of Flooding of Less than one percent.

According to the 1997 Uniform Building Code Seismic Zone Map of the United States, the property is located in Seismic Zone 4, defined as an area of high probability of damaging ground motion.

According to the Wind Zone Map, published by the Federal Emergency Management Agency (FEMA), the property is located in Zone I and is not located in a Hurricane-Susceptible Region or Special Wind Region.

## 4. EXISTING BUILDING ASSESSMENT

---

### 4.1. SPACE TYPES

All 36,996 square feet of the building are owned by the Ocean View Unified School District, and occupied by Circle View Elementary School. The spaces are mostly, classrooms, multi-purpose rooms, Cafetorium, supporting restrooms, administrative offices, mechanical and other utility spaces. The site has four (6) portable classrooms and one (1) portable restroom building delivered in 1995. Three (3) classrooms have a pitched metal roof, one (1) classroom has a flat asphalt shingle roof, and the rest room has pitched asphalt roof. All buildings are wood frame construction, wood panel exterior walls, aluminum windows, and solid wood doors.

### 4.2. INACCESSIBLE AREAS OR KEY SPACES NOT OBSERVED

The entire school was observed in order to gain a clear understanding of the property's overall condition. Other areas accessed included the site within the property boundaries, exterior of the property and the roof. All areas of the property were available for observation during the site visit. Site Improvements

## 5. SITE IMPROVEMENTS

### 5.1. UTILITIES

The following table identifies the utility suppliers and the condition and adequacy of the services.

SITE UTILITIES		
UTILITY	SUPPLIER	CONDITION AND ADEQUACY
Sanitary sewer	City of Huntington Beach	Good
Storm sewer	City of Huntington Beach	Good
Domestic water	City of Huntington Beach	Good
Electric service	Southern California Edison	Good
Natural gas service	Southern California Gas	Good

#### Actions/Comments:

- According to the Client's representative, the utilities provided are adequate for the property. There are no unique, onsite utility systems such as emergency electrical generators, septic systems, water or waste water treatment plants, or propane gas tanks.

### 5.2. PARKING, PAVING, AND SIDEWALKS

ITEM	DESCRIPTION
Main Ingress and Egress	Hooker Drive
Access from	South
Additional Entrances	None
Additional Access from	East

PAVING AND FLATWORK			
ITEM	MATERIAL	LAST WORK DONE	CONDITION
Entrance Driveway Apron	Concrete	1965	Excellent
Parking Lot	Asphalt	2014	Good
Drive Aisles	Asphalt	2014	Good
Service Aisles	Asphalt	2014	Good
Sidewalks	Concrete	1965	Good
Curbs	Concrete	1965	Good
Site Stairs	None	N/A	--
Pedestrian Ramps	None	N/A	--

## FACILITY CONDITION ASSESSMENT

CIRCLE VIEW ELEMENTARY  
6261 HOOKER DRIVE  
HUNTINGTON BEACH, CALIFORNIA 92647

EMG PROJECT NO: 119317.16R000-001.017

PARKING COUNT				
OPEN LOT	CARPORT	PRIVATE GARAGE	SUBTERRANEAN GARAGE	FREESTANDING PARKING STRUCTURE
36	0	0	0	0
Total Number of ADA Compliant Spaces			4	
Number of ADA Compliant Spaces for Vans			2	
Total Parking Spaces			36	
Parking Ratio (Spaces/Thousand SF)			.68	
Method of Obtaining Parking Count			Physical count	

### Anticipated Lifecycle Replacements:

- Asphalt seal coating

### Actions/Comments:

No significant actions are identified at the present time. On-going periodic maintenance is highly recommended.

- The asphalt pavement exhibits isolated areas of failure and deterioration, such as alligator cracking, and localized depressions.
- The concrete sidewalks have isolated areas of vertically displaced concrete due to settlement.

## 5.3. DRAINAGE SYSTEMS AND EROSION CONTROL

DRAINAGE SYSTEM AND EROSION CONTROL		
SYSTEM	EXISTS AT SITE	CONDITION
Surface Flow	<input checked="" type="checkbox"/>	Good
Inlets	<input checked="" type="checkbox"/>	Good
Swales	<input type="checkbox"/>	--
Detention pond	<input type="checkbox"/>	--
Lagoons	<input type="checkbox"/>	--
Ponds	<input type="checkbox"/>	--
Underground Piping	<input checked="" type="checkbox"/>	Good
Pits	<input type="checkbox"/>	--
Municipal System	<input checked="" type="checkbox"/>	Good
Dry Well	<input type="checkbox"/>	--

## FACILITY CONDITION ASSESSMENT

CIRCLE VIEW ELEMENTARY  
6261 HOOKER DRIVE  
HUNTINGTON BEACH, CALIFORNIA 92647

EMG PROJECT NO: 119317.16R000-001.017

### 5.4. TOPOGRAPHY AND LANDSCAPING

ITEM	DESCRIPTION						
Site Topography	Slopes gently down from the north side of the property to the south property line.						
Landscaping	Trees	Grass	Flower Beds	Planters	Drought Tolerant Plants	Decorative Stone	None
	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Landscaping Condition	Good						
Irrigation	Automatic Underground		Drip		Hand Watering		None
	<input checked="" type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>
Irrigation Condition	Good						
RETAINING WALLS							
TYPE		LOCATION				CONDITION	
None		NA				--	

#### Anticipated Lifecycle Replacements:

- Irrigation system components

#### Actions/Comments:

- The topography and adjacent uses do not appear to present conditions detrimental to the property. There are no significant areas of erosion.
- The underground irrigation system has a history of maintenance requirements. Isolated areas of the irrigation system must be repaired and restored.

### 5.5. GENERAL SITE IMPROVEMENTS

PROPERTY SIGNAGE	
Property Signage	Pylon
Street Address Displayed?	Yes

SITE AND BUILDING LIGHTING					
Site Lighting	None	Pole Mounted	Bollard Lights	Ground Mounted	Parking Lot Pole Type
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	Overall Site Lighting Condition			Good	
Building Lighting	None		Wall Mounted		Recessed Soffit
	<input type="checkbox"/>		<input checked="" type="checkbox"/>		<input type="checkbox"/>
	Overall Building Lighting Condition			Good	

## FACILITY CONDITION ASSESSMENT

CIRCLE VIEW ELEMENTARY  
6261 HOOKER DRIVE  
HUNTINGTON BEACH, CALIFORNIA 92647

EMG PROJECT NO: 119317.16R000-001.017

SITE FENCING		
TYPE	LOCATION	CONDITION
Chain link with metal posts	Perimeter of Property	Fair

REFUSE DISPOSAL				
Refuse Disposal			Common area dumpsters	
Dumpster Locations	Mounting	Enclosure	Contracted	Condition
South Entrance	Concrete pad	CMU fence	Yes	Good

OTHER SITE AMENITIES			
	DESCRIPTION	LOCATION	CONDITION
Playground Equipment	Plastic and metal	SW Area of Property	Fair
Tennis Courts	None	NA	--
Basketball Court	None	NA	--
Swimming Pool	None	NA	--

### ***Anticipated Lifecycle Replacements:***

- Site fencing

### ***Actions/Comments:***

- Future lifecycle replacements of the components listed above will be required.
- The chain-link site fencing has isolated portions of the fence that are damaged and weathered. The affected portions of the fence should be replaced.



## 6. BUILDING ARCHITECTURAL AND STRUCTURAL SYSTEMS

### 6.1. FOUNDATIONS

BUILDING FOUNDATION		
ITEM	DESCRIPTION	CONDITION
Foundation	Slab on grade with integral footings	Good
Basement and Crawl Space	None	--

**Anticipated Lifecycle Replacements:**

- No components of significance.

**Actions/Comments:**

- There are no significant signs of settlement, deflection, or movement.

### 6.2. SUPERSTRUCTURE

BUILDING SUPERSTRUCTURE		
ITEM	DESCRIPTION	CONDITION
Framing / Load-Bearing Walls	Steel columns and beams	Good
Ground Floor	Concrete slab	Good
Roof Framing	Steel beams or girders	Good
Roof Decking	Metal decking	Good

**Anticipated Lifecycle Replacements:**

- No components of significance

**Actions/Comments:**

- The superstructure is concealed. Walls and floors appear to be plumb, level, and stable. There are no significant signs of deflection or movement.

### 6.3. ROOFING

PRIMARY ROOF			
Type / Geometry	Flat or low-sloping	Finish	Single-ply TPO/PVC
Maintenance	In-house staff	Roof Age	1 year
Flashing	Flashings match main membrane	Warranties	No

## FACILITY CONDITION ASSESSMENT

CIRCLE VIEW ELEMENTARY  
6261 HOOKER DRIVE  
HUNTINGTON BEACH, CALIFORNIA 92647

EMG PROJECT NO: 119317.16R000-001.017

PRIMARY ROOF			
Parapet Copings	No copings; exposed	Roof Drains	Internal drains
Fascia	Metal	Insulation	Could not be determined
Soffits	Exposed	Skylights	No
Attics	No	Ponding	No
Ventilation Source-1	None	Leaks Observed	No
Ventilation Source-2	--	Roof Condition	Fair

The primary roof is located at 17251 Golden View.

SECONDARY ROOF			
Type / Geometry	Flat or low-sloping	Finish	Modified bituminous
Maintenance	In-house staff	Roof Age	Unknown
Flashing	Sheet metal	Warranties	No
Parapet Copings	NA; no parapet walls	Roof Drains	Edge drainage to ground
Fascia	None	Insulation	None
Soffits	Exposed	Skylights	No
Attics	No	Ponding	No
Ventilation Source-1	Gravity vents	Leaks Observed	No
Ventilation Source-2	--	Roof Condition	Fair

The secondary roof is located at the portables.

### **Anticipated Lifecycle Replacements:**

- Asphalt shingles on Portable
- Roof membrane.

### **Actions/Comments:**

- According to the Client's representative, the roof finishes were reportedly installed in 1972 original with an elastomeric coating applied in 2015. Information regarding roof warranties or bonds was not available and there are no active roof leaks.
- The Number1 portable building has an asphalt roll roof and appears to be weathering. This unit is located on the west side of the main building.

## FACILITY CONDITION ASSESSMENT

CIRCLE VIEW ELEMENTARY  
6261 HOOKER DRIVE  
HUNTINGTON BEACH, CALIFORNIA 92647

EMG PROJECT NO: 119317.16R000-001.017

### 6.4. EXTERIOR WALLS

BUILDING EXTERIOR WALLS		
TYPE	LOCATION	CONDITION
Primary Finish	Brick veneer	Good
Secondary Finish	Wood siding	Good
Accented with	Decorative tile or stone veneer	Good
Soffits	Exposed	Good

Building sealants (caulking) are located between dissimilar materials, at joints, and around window and door openings.

#### ***Anticipated Lifecycle Replacements:***

- Paint Panels

#### ***Actions/Comments:***

- No significant actions are identified at the present time. On-going periodic maintenance, including re-caulking, is highly recommended. Future lifecycle replacements of the components listed above will be required.
- The wood panels appear to be original and are in good condition.

### 6.5. EXTERIOR AND INTERIOR STAIRS

Exterior concrete stairs are in good condition

### 6.6. EXTERIOR WINDOWS AND DOORS

BUILDING WINDOWS				
WINDOW FRAMING	GLAZING	LOCATION	WINDOW SCREEN	CONDITION
Aluminum framed storefront	Single pane	Admin Building	<input type="checkbox"/>	Good
Aluminum framed, fixed	Single pane	Throughout Buildings	<input type="checkbox"/>	Good
Aluminum framed, fixed	Single pane	Portables	<input type="checkbox"/>	Fair

BUILDING DOORS		
Main Entrance Doors	Door Type	Condition
	Fully glazed, metal framed	Good
Secondary Entrance Doors	Metal, hollow	Good
Service Doors	Metal, hollow	Good

## FACILITY CONDITION ASSESSMENT

CIRCLE VIEW ELEMENTARY  
6261 HOOKER DRIVE  
HUNTINGTON BEACH, CALIFORNIA 92647

EMG PROJECT NO: 119317.16R000-001.017

### ***Anticipated Lifecycle Replacements:***

- Exterior doors
- Exterior windows

### ***Actions/Comments:***

- There are a few damaged doors and door frames. The damaged doors must be replaced.
- The windows are antiquated, energy-inefficient units with single-pane glazing.
- The windows display isolated evidence of leaks. The cost to repair the windows is relatively insignificant and the work can be performed as part of the property management's routine maintenance and operations program.

## 6.7. PATIO, TERRACE, AND BALCONY

Not applicable. There are no patios, terraces, or balconies.

## FACILITY CONDITION ASSESSMENT

CIRCLE VIEW ELEMENTARY  
6261 HOOKER DRIVE  
HUNTINGTON BEACH, CALIFORNIA 92647

EMG PROJECT NO: 119317.16R000-001.017

## 7. BUILDING MECHANICAL AND PLUMBING SYSTEMS

See the Mechanical Equipment List in the Appendices for the quantity, manufacturer's name, model number, capacity and year of manufacturer of the major mechanical equipment, if available.

### 7.1. BUILDING HEATING, VENTILATING, AND AIR CONDITIONING (HVAC)

INDIVIDUAL UNITS	
Primary Components	Package units
Cooling (if separate from above)	performed via components above
Quantity and Capacity Ranges	5 units ranging from 20 tons to 25 tons
Total Heating or Cooling Capacity	120 tons
Heating Fuel	Natural gas
Location of Equipment	Rooftop
Space Served by System	Entire building
Age Ranges	All units dated 1999
Primary Component Condition	Fair

CONTROLS AND VENTILATION	
HVAC Control System	Individual non-programmable thermostats/controls
HVAC Control System Condition	Poor
Building Ventilation	Rooftop exhaust fans
Ventilation System Condition	Excellent

#### **Anticipated Lifecycle Replacements:**

- Package units

#### **Actions/Comments:**

- The HVAC systems are maintained by the in-house maintenance staff. Records of the installation, maintenance, upgrades, and replacement of the HVAC equipment at the property have been maintained since the property was first occupied.
- The HVAC equipment appears have been installed in 1999. HVAC equipment is replaced on an "as needed" basis.
- A DDC System should be installed.

### 7.2. BUILDING PLUMBING AND DOMESTIC HOT WATER

BUILDING PLUMBING SYSTEM		
TYPE	DESCRIPTION	CONDITION
Water Supply Piping	Copper	Good

## FACILITY CONDITION ASSESSMENT

CIRCLE VIEW ELEMENTARY  
6261 HOOKER DRIVE  
HUNTINGTON BEACH, CALIFORNIA 92647

EMG PROJECT NO: 119317.16R000-001.017

BUILDING PLUMBING SYSTEM		
TYPE	DESCRIPTION	CONDITION
Waste/Sewer Piping	Cast iron	Good
Vent Piping	Cast iron	Good
Water Meter Location	Vault	

DOMESTIC WATER HEATERS OR BOILERS	
Components	Water Heaters
Fuel	Natural gas
Quantity and Input Capacity	Unknown
Storage Capacity	40 gallons
Adequacy of Hot Water	Adequate
Adequacy of Water Pressure	Adequate

PLUMBING FIXTURES	
Water Closets	Commercial
Toilet (Water Closet) Flush Rating	1.2 GPF
Common Area Faucet Nominal Flow Rate	2.0 GPM
Condition	Excellent

### **Anticipated Lifecycle Replacements:**

- Water heaters
- Toilets
- Urinals
- Sinks

### **Actions/Comments:**

- The plumbing systems appear to be well maintained and functioning adequately. The water pressure appears to be sufficient. No significant repair actions or short term replacement costs are required. Routine and periodic maintenance is recommended. Future lifecycle replacements of the components or systems listed above will be required.

## 7.3. BUILDING GAS DISTRIBUTION

Gas service is supplied from the gas main on the adjacent public street. The gas meters and regulators are located at the main shut-off vault. The gas distribution piping within each building is malleable steel (black iron).

## 7.4. BUILDING ELECTRICAL

BUILDING ELECTRICAL SYSTEMS			
Electrical Lines	Underground	Transformer	Pad-mounted

## FACILITY CONDITION ASSESSMENT

CIRCLE VIEW ELEMENTARY  
6261 HOOKER DRIVE  
HUNTINGTON BEACH, CALIFORNIA 92647

EMG PROJECT NO: 119317.16R000-001.017

BUILDING ELECTRICAL SYSTEMS			
Main Service Size	800 amps	Volts	277/480 Volt, three-phase
Meter & Panel Location	West Side of Property	Branch Wiring	Copper
Conduit	Metallic	Step-Down Transformers?	Yes
Security / Surveillance System?	No	Building Intercom System?	Yes
Lighting Fixtures	T-8		
Main Distribution Condition	Good		
Secondary Panel and Transformer Condition	Good		
Lighting Condition	Good		

### Anticipated Lifecycle Replacements:

- Circuit breaker panels
- Main switchgear
- Switchboards
- Step-down transformers
- Interior light fixtures

### Actions/Comments:

- The onsite electrical systems up to the meters are owned and maintained by the respective utility company.
- The panels, switchboards, and step-down transformers are mostly original 1965 components; some were upgraded in 2002/4, and are reportedly adequate for the facility's needs. However, due to the age of the panels and increasing difficulty of obtaining replacement parts over time, lifecycle replacements are recommended per above.

## 7.5. BUILDING ELEVATORS AND CONVEYING SYSTEMS

Not applicable. There are no elevators or conveying systems.

## 7.6. FIRE PROTECTION AND SECURITY SYSTEMS

ITEM	DESCRIPTION					
Type	None					
Fire Alarm System	Central Alarm Panel	<input checked="" type="checkbox"/>	Battery-Operated Smoke Detectors	<input type="checkbox"/>	Alarm Horns	<input checked="" type="checkbox"/>
	Annunciator Panels	<input checked="" type="checkbox"/>	Hard-Wired Smoke Detectors	<input checked="" type="checkbox"/>	Strobe Light Alarms	<input checked="" type="checkbox"/>
	Pull Stations	<input checked="" type="checkbox"/>	Emergency Battery-Pack Lighting	<input checked="" type="checkbox"/>	Illuminated EXIT Signs	<input checked="" type="checkbox"/>
Alarm System Condition	--					
Sprinkler System	None	<input checked="" type="checkbox"/>	Standpipes	<input type="checkbox"/>	Backflow Preventer	<input type="checkbox"/>
	Hose Cabinets	<input type="checkbox"/>	Fire Pumps	<input type="checkbox"/>	Siamese Connections	<input type="checkbox"/>
Suppression Condition	--					



## FACILITY CONDITION ASSESSMENT

CIRCLE VIEW ELEMENTARY  
6261 HOOKER DRIVE  
HUNTINGTON BEACH, CALIFORNIA 92647

EMG PROJECT NO: 119317.16R000-001.017

ITEM	DESCRIPTION			
Type	None			
Central Alarm Panel System	Location of Alarm Panel		Installation Date of Alarm Panel	
	Administration Office		August 2015	
Fire Extinguishers	Last Service Date		Servicing Current?	
	12/10/15		Yes	
Hydrant Location	On City Street			
Siamese Location	Unknown			
Special Systems	Kitchen Suppression System	<input type="checkbox"/>	Computer Room Suppression System	<input type="checkbox"/>

### Anticipated Lifecycle Replacements:

- Central alarm panel
- Alarm devices and system

### Actions/Comments:

- The central alarm panel appears to be in good condition and is serviced regularly by a qualified fire equipment contractor. Equipment testing is not within the scope of a Facility Condition Assessment. Based on inspection documents displayed by the panel, the central alarm panel has been inspected within the last year. Fire alarm panels contain sophisticated electronic circuits that are constantly energized. Over time, circuit components deteriorate or become obsolete. Even though an alarm panel may continue to function well past its estimated design life, replacement parts may become difficult to obtain and in many cases the alarm panel will not communicate with new devices it is supposed to monitor. Replacement is recommended during the reserve term. No significant actions are identified at the present time. On-going periodic maintenance is highly recommended.

## 8. INTERIOR SPACES

### 8.1. INTERIOR FINISHES

The facility is used as a school.

The most significant interior spaces include classroom buildings (pods), restroom buildings, library, MPR, and administration building. Supporting areas include employee break rooms, mechanical rooms, and utility closets.

The following table generally describes the locations and typical conditions of the interior finishes within the facility:

TYPICAL FLOOR FINISHES		
FLOOR FINISH	LOCATIONS	GENERAL CONDITION
Vinyl tile	Waiting area in admin	Good
Carpet	offices, classrooms	Fair
Ceramic tile	restrooms	Good
TYPICAL WALL FINISHES		
WALL FINISH	LOCATIONS	GENERAL CONDITION
Painted drywall	offices, classrooms, restrooms	Good
Ceramic tile	restrooms	Good
TYPICAL CEILING FINISHES		
CEILING FINISH	LOCATIONS	GENERAL CONDITION
Suspended T-Bar (acoustic tile)	offices, classrooms, administration	Good
Painted drywall	restrooms	Good
INTERIOR DOORS		
ITEM	TYPE	CONDITION
Interior Doors	Solid core wood	Good
Door Framing	Metal	Good
Fire Doors	Yes	Good

#### Anticipated Lifecycle Replacements:

- Carpet
- Sheet vinyl
- Interior paint
- Suspended acoustic ceiling tile

#### Actions/Comments:

- It appears that the interior finishes are original, some upgrades in 2004, with Restrooms upgraded in 2015.

## FACILITY CONDITION ASSESSMENT

CIRCLE VIEW ELEMENTARY  
6261 HOOKER DRIVE  
HUNTINGTON BEACH, CALIFORNIA 92647

EMG PROJECT NO: 119317.16R000-001.017

### 8.2. FURNITURE, FIXTURES AND EQUIPMENT (FF&E)

The school's furniture, fixtures and equipment (FF&E) consist of casework, marker and tack boards, screens and projectors, shelving, desks, tables and chairs, computers, task lights and bleachers. Other than casework, assessment of FF&E is not included in the scope of work.

#### **Anticipated Lifecycle Replacements:**

- No components of significance

### 8.3. COMMERCIAL KITCHEN EQUIPMENT

The cafeteria area has a variety of commercial kitchen appliances, fixtures, and equipment. The equipment is owned and maintained in-house.

The cafeteria kitchen includes the following major appliances, fixtures, and equipment:

COMMERCIAL KITCHEN		
APPLIANCE	COMMENT AND CONDITION	
Refrigerators	Up-right	Good
Freezers	Walk-in	Good
Ranges	Gas	Good
Ovens	Electric	Good
Griddles / Grills	Electric	Good
Fryers	None	Good
Hood	Exhaust ducted to exterior	Good
Dishwasher	<input type="checkbox"/>	--
Microwave	<input checked="" type="checkbox"/>	Good
Ice Machines	<input checked="" type="checkbox"/>	Good
Steam Tables	<input checked="" type="checkbox"/>	--
Work Tables	<input type="checkbox"/>	--
Shelving	<input checked="" type="checkbox"/>	Good

#### **Anticipated Lifecycle Replacements:**

- Cooking Range
- Convection oven
- Walk-in freezer
- Walk-in cooler
- Steam kettle
- Ice maker

#### **Actions/Comments:**

- No significant actions are identified at the present time. On-going periodic maintenance is highly recommended.

## 9. OTHER STRUCTURES

---

Not applicable. There are no major accessory structures.

## FACILITY CONDITION ASSESSMENT

CIRCLE VIEW ELEMENTARY  
6261 HOOKER DRIVE  
HUNTINGTON BEACH, CALIFORNIA 92647

EMG PROJECT NO: 119317.16R000-001.017

## CERTIFICATION

---

DLR Group retained EMG to perform this Facility Condition Assessment in connection with its Facilities Master Planning Project for the Ocean View School District at 6261 Hooker Drive, Huntington Beach, CA 92647, the "Property". It is our understanding that the primary interest of DLR Group is to locate and evaluate materials and building system defects that might significantly affect the value of the property and to determine if the present Property has conditions that will have a significant impact on its continued operations.

The conclusions and recommendations presented in this report are based on the brief review of the plans and records made available to our Project Manager during the site visit, interviews of available property management personnel and maintenance contractors familiar with the Property, appropriate inquiry of municipal authorities, our Project Manager's walk-through observations during the site visit, and our experience with similar properties.

No testing, exploratory probing, dismantling or operating of equipment or in depth studies were performed unless specifically required under Section 2 of this report. This assessment did not include engineering calculations to determine the adequacy of the Property's original design or existing systems. Although walk-through observations were performed, not all areas were observed (See Section 4.2 for areas observed). There may be defects in the Property, which were in areas not observed or readily accessible, may not have been visible, or were not disclosed by management personnel when questioned. The report describes property conditions at the time that the observations and research were conducted.

This report has been prepared on behalf of and exclusively for the use of DLR Group for the purpose stated within Section 2 of this report. The report, or any excerpt thereof, shall not be used by any party other than DLR Group or for any other purpose than that specifically stated in our agreement or within Section 2 of this report without the express written consent of EMG.

Any reuse or distribution of this report without such consent shall be at DLR Group and the recipient's sole risk, without liability to EMG.

**Prepared by:** Steve Novotny,  
Project Manager

**Reviewed by:**



---

George Luce  
Technical Report Reviewer  
[gluce@emgcorp.com](mailto:gluce@emgcorp.com) 800.733.0660 x6261

## 10. APPENDICES

---

APPENDIX A: PHOTOGRAPHIC RECORD

APPENDIX B: SITE PLAN

APPENDIX C: SUPPORTING DOCUMENTATION

APPENDIX D: EMG ABBREVIATED ADA CHECKLIST

APPENDIX E: PRE-SURVEY QUESTIONNAIRE

## FACILITY CONDITION ASSESSMENT

CIRCLE VIEW ELEMENTARY  
6261 HOOKER DRIVE  
HUNTINGTON BEACH, CALIFORNIA 92647

EMG PROJECT NO: 119317.16R000-001.017

---

---

# APPENDIX A: PHOTOGRAPHIC RECORD

---



# FACILITIES CONDITION ASSESSMENT PHOTOGRAPHIC RECORD

CIRCLE VIEW ELEMENTARY

EMG PROJECT NO: 119317.16R000-001.017



Photo #1: Circle View Entrance



Photo #2: Circle View Parking



Photo #3: MPR Building



Photo #4: MPR Split Unit Condensers



Photo #5: MPR Furnace and AC




Photo #6: HVAC Controls

# FACILITIES CONDITION ASSESSMENT PHOTOGRAPHIC RECORD

CIRCLE VIEW ELEMENTARY

EMG PROJECT NO: 119317.16R000-001.017



Photo #7: MPR West Exterior



Photo #8: Main Electrical Room



Photo #9: Electrical Main Disconnect



Photo #10: ITE Imperial Panels



Photo #11: American Water Heater – 40 Gal - 1992



Photo #12: Copper and Galvanized Domestic Water Piping



# FACILITIES CONDITION ASSESSMENT PHOTOGRAPHIC RECORD

CIRCLE VIEW ELEMENTARY

EMG PROJECT NO: 119317.16R000-001.017



Photo #13: MPR Building Suspended Ceiling



Photo #14: Exit Doors from Auditorium




Photo #15: VCT in Auditorium



Photo #16: Metal Window Frames




Photo #17: Exterior Stairs from Stage Area




Photo #18: Food Cooler

# FACILITIES CONDITION ASSESSMENT PHOTOGRAPHIC RECORD

CIRCLE VIEW ELEMENTARY

EMG PROJECT NO: 119317.16R000-001.017



Photo #19: Admin Building



Photo #20: Admin Bldg. Men's Rest Room



Photo #21: Admin Bldg. Urinal




Photo #22: Admin Bldg. Sink



Photo #23: Food Prep Area



Photo #24: West Elevation of MPR



# FACILITIES CONDITION ASSESSMENT PHOTOGRAPHIC RECORD

CIRCLE VIEW ELEMENTARY

EMG PROJECT NO: 119317.16R000-001.017



Photo #25: Classroom Exterior



Photo #26: Classroom Interior (typical)



Photo #27: Classroom Sink (typical)



Photo #28: Classroom Entrance Door




Photo #29: VCT in Center of Classroom Pods




Photo #30: Acoustical Ceiling Tiles

# FACILITIES CONDITION ASSESSMENT PHOTOGRAPHIC RECORD

CIRCLE VIEW ELEMENTARY

EMG PROJECT NO: 119317.16R000-001.017



Photo #31: New Boys Rest Room



Photo #32: New Boys Rest Room



Photo #33: Domestic Water Heater



Photo #34: Classroom Pod Carpeting and VCT



Photo #35: Classroom Ceiling and Light Fixture



Photo #36: Kindergarten Rest Room



# FACILITIES CONDITION ASSESSMENT PHOTOGRAPHIC RECORD

CIRCLE VIEW ELEMENTARY

EMG PROJECT NO: 119317.16R000-001.017



Photo #37: Classroom VCT



Photo #38: Kids Club East Elevation



Photo #39: Pedestrian Walk Deficiency



Photo #40: Kids Club Carpeting



Photo #41: MarvAir Heat Pump



Photo #42: Class Room Pod - 004

# FACILITIES CONDITION ASSESSMENT PHOTOGRAPHIC RECORD

CIRCLE VIEW ELEMENTARY

EMG PROJECT NO: 119317.16R000-001.017



Photo #43: Class Room Carpet - 004



Photo #44: Portable Building - Library



Photo #45: Library Panelboard



Photo #46: Library Suspended Ceiling




Photo #47: Library HVAC Diffuser



Photo #48: MPR Package Unit



# FACILITIES CONDITION ASSESSMENT PHOTOGRAPHIC RECORD

CIRCLE VIEW ELEMENTARY

EMG PROJECT NO: 119317.16R000-001.017



Photo #49: Admin Building Condensing Unit



Photo #50: Fire Panel – Admin Building



Photo #51: Acoustic Ceiling Tiles



Photo #52: Brick facade



Photo #53: Lavatories in Rest room



Photo #54:

# FACILITIES CONDITION ASSESSMENT PHOTOGRAPHIC RECORD

CIRCLE VIEW ELEMENTARY

EMG PROJECT NO: 119317.16R000-001.017



Photo #55: Classroom panelboard



Photo #56: Condensing Unit



Photo #57: Wall mounted package unit for Pod



Photo #58: Roof



Photo #59: Carrier RTU – 25 Ton (typical)



Photo #60: Elastomeric Roof Coating (typical)

## FACILITY CONDITION ASSESSMENT

CIRCLE VIEW ELEMENTARY  
6261 HOOKER DRIVE  
HUNTINGTON BEACH, CALIFORNIA 92647

EMG PROJECT NO: 119317.16R000-001.017

---

---

## APPENDIX B: SITE PLAN

---



## FACILITY CONDITION ASSESSMENT

CIRCLE VIEW ELEMENTARY  
6261 HOOKER DRIVE  
HUNTINGTON BEACH, CALIFORNIA 92647

EMG PROJECT NO: 119317.16R000-001.017

---

---

## **APPENDIX C:** **SUPPORTING DOCUMENTATION**


---



FACILITIES CONDITION ASSESSMENT  
AERIAL SITE PLAN

CIRCLE VIEW ELEMENTARY

EMG PROJECT NO: 119319.16R-001.017



SOURCE:  
Google Maps: Imagery ©2016 Google, Map data ©2016 Google




ON-SITE DATE:  
May 4, 2016



# FACILITIES CONDITION ASSESSMENT FLOOD MAP

CIRCLE VIEW ELEMENTARY

EMG PROJECT NO: 119317.16R000-001.017



SOURCE:

FEMA Panel No.: 232 of 539 Dated: December 3, 2009  
Map Number 06059C0232J

ON-SITE DATE:

May 4, 2016

## FACILITY CONDITION ASSESSMENT

CIRCLE VIEW ELEMENTARY  
6261 HOOKER DRIVE  
HUNTINGTON BEACH, CALIFORNIA 92647

EMG PROJECT NO: 119317.16R000-001.017

---

---

## **APPENDIX D:** **EMG ABBREVIATED ADA CHECKLIST**

---



# FACILITY CONDITION ASSESSMENT

CIRCLE VIEW ELEMENTARY  
6261 HOOKER DRIVE  
HUNTINGTON BEACH, CALIFORNIA 92647

EMG PROJECT NO: 119317.16R000-001.017

**PROPERTY NAME:** Circle View Elementary School

**DATE:** May 4, 2016

**PROJECT NUMBER:** 119317.16R000.001.017

EMG ABBREVIATED ADA CHECKLIST					
	BUILDING HISTORY	YES	NO	N/A	COMMENTS
1.	Has the management previously completed an ADA review?		<input type="checkbox"/>		
2.	Have any ADA improvements been made to the property?				
3.	Does a Barrier Removal Plan exist for the property?				
4.	Has the Barrier Removal Plan been reviewed/approved by an arms-length third party such as an engineering firm, architectural firm, building department, other agencies, etc.?				
5.	Has building ownership or management received any ADA related complaints that have not been resolved?				
6.	Is any litigation pending related to ADA issues?				
	PARKING	YES	NO	N/A	COMMENTS
1.	Are there sufficient parking spaces with respect to the total number of reported spaces?				
2.	Are there sufficient van-accessible parking spaces available (96" wide/ 96" aisle for van)?				
3.	Are accessible spaces marked with the International Symbol of Accessibility? Are there signs reading "Van Accessible" at van spaces?				
4.	Is there at least one accessible route provided within the boundary of the site from public transportation stops, accessible parking spaces, passenger loading zones, if provided, and public streets and sidewalks?				
5.	Do curbs on the accessible route have depressed, ramped curb cuts at drives, paths, and drop-offs?				
6.	Does signage exist directing you to accessible parking and an accessible building entrance?				
	RAMPS	YES	NO	N/A	COMMENTS
1.	If there is a ramp from parking to an accessible building entrance, does it meet slope requirements? (1:12)				
2.	Are ramps longer than 6 ft complete with railings on both sides?				
3.	Is the width between railings at least 36 inches?				
4.	Is there a level landing for every 30 ft horizontal length of ramp, at the top and at the bottom of ramps and switchbacks?				
	ENTRANCES/EXITS	YES	NO	N/A	COMMENTS
1.	Is the main accessible entrance doorway at least 32 inches wide?				
2.	If the main entrance is inaccessible, are there alternate accessible entrances?				
3.	Can the alternate accessible entrance be used independently?				

# FACILITY CONDITION ASSESSMENT

CIRCLE VIEW ELEMENTARY  
6261 HOOKER DRIVE  
HUNTINGTON BEACH, CALIFORNIA 92647

EMG PROJECT NO: 119317.16R000-001.017

	ENTRANCES/EXITS	YES	NO	N/A	COMMENTS
4.	Is the door hardware easy to operate (lever/push type hardware, no twisting required, and not higher than 48 inches above the floor)?				
5.	Are main entry doors other than revolving door available?				
6.	If there are two main doors in series, is the minimum space between the doors 48 inches plus the width of any door swinging into the space?				
	PATHS OF TRAVEL	YES	NO	N/A	COMMENTS
1.	Is the main path of travel free of obstruction and wide enough for a wheelchair (at least 36 inches wide)?				
2.	Does a visual scan of the main path reveal any obstacles (phones, fountains, etc.) that protrude more than 4 inches into walkways or corridors?				
3.	Are floor surfaces firm, stable, and slip resistant (carpets wheelchair friendly)?				
4.	Is at least one wheelchair-accessible public telephone available?				
5.	Are wheelchair-accessible facilities (toilet rooms, exits, etc.) identified with signage?				
6.	Is there a path of travel that does not require the use of stairs?				
7.	If audible fire alarms are present, are visual alarms (strobe light alarms) also installed in all common areas?				
	ELEVATORS	YES	NO	N/A	COMMENTS
1.	Do the call buttons have visual signals to indicate when a call is registered and answered?				
2.	Are there visual and audible signals inside cars indicating floor change?				
3.	Are there standard raised and Braille marking on both jambs of each host way entrance?				
4.	Do elevator doors have a reopening device that will stop and reopen a car door if an object or a person obstructs the door?				
5.	Do elevator lobbies have visual and audible indicators of car arrival?				
6.	Does the elevator interior provide sufficient wheelchair turning area (51" x 68")?				
7.	Are elevator controls low enough to be reached from a wheelchair (48 inches front approach/54 inches side approach)?				
8.	Are elevator control buttons designated by Braille and by raised standard alphabet characters (mounted to the left of the button)?				
9.	If a two-way emergency communication system is provided within the elevator cab, is it usable without voice communication?				
	RESTROOMS	YES	NO	N/A	COMMENTS
1.	Are common area public restrooms located on an accessible route?				

## FACILITY CONDITION ASSESSMENT

CIRCLE VIEW ELEMENTARY  
6261 HOOKER DRIVE  
HUNTINGTON BEACH, CALIFORNIA 92647

EMG PROJECT NO: 119317.16R000-001.017

	RESTROOMS	YES	NO	N/A	COMMENTS
2.	Are pull handles push/pull or lever type?				
3.	Are there audible and visual fire alarm devices in the toilet rooms?				
4.	Are corridor access doors wheelchair-accessible (at least 32 inches wide)?				
5.	Are public restrooms large enough to accommodate a wheelchair turnaround (60" turning diameter)?				
6.	In unisex toilet rooms, are there safety alarms with pull cords?				
7.	Are stall doors wheelchair accessible (at least 32" wide)?				
8.	Are grab bars provided in toilet stalls?				
9.	Are sinks provided with clearance for a wheelchair to roll under (29" clearance)?				
10.	Are sink handles operable with one hand without grasping, pinching or twisting?				
11.	Are exposed pipes under sink sufficiently insulated against contact?				
12.	Are soap dispensers, towel, etc. reachable (48" from floor for frontal approach, 54" for side approach)?				
13.	Is the base of the mirror no more than 40" from the floor?				

## FACILITY CONDITION ASSESSMENT

CIRCLE VIEW ELEMENTARY  
6261 HOOKER DRIVE  
HUNTINGTON BEACH, CALIFORNIA 92647

EMG PROJECT NO: 119317.16R000-001.017

---

---

## APPENDIX E: PRE-SURVEY QUESTIONNAIRE

---

FACILITY CONDITION ASSESSMENT: PRE-SURVEY QUESTIONNAIRE

This questionnaire must be completed by the property owner, the owner's designated representative, or someone knowledgeable about the subject property. *The completed form must be presented to EMG's Field Observer on the day of the site visit.* If the form is not completed, EMG's Project Manager will require *additional time* during the on-site visit with such a knowledgeable person in order to complete the questionnaire. During the site visit, EMG's Field Observer may ask for details associated with selected questions. This questionnaire will be utilized as an exhibit in EMG's final Property Condition Report.

Name of person completing form: NOAH VALADEZ - STENO NOVOTNY  
Title / Association with property: ASSOCIATE  
Length of time associated w/ property: 25 YEARS  
Date Completed: 9/4/16  
Phone Number: 714-349-1882  
Building / Facility Name: CIRCLO VION 001.017


Directions: Please answer all questions to the best of your knowledge and in good faith. Please provide additional details in the Comments column, or backup documentation for any Yes responses.

DATA OVERVIEW		RESPONSE
1	Year constructed	MAIN 1965 - PORT 97-98-10 - RR 2015
2	Building size in SF	ALL BLDGS - 53,275 + RR -
3	Replacement Value	
4	Acreage	
5	Number of parking spaces	
6	Age of roof (known or estimated); active warranty w/ expiration date?	8/2015 BUILTUP, BLATOWIRIC
QUESTION		RESPONSE
7	List all major renovations or rehabilitations since construction (with estimated dates).	NOW STUDENT RR BLDGS 2015 FIRE ALARM, ROOFS
8	List other somewhat lesser but still significant capital improvements, focused within recent years (provide approximate year completed).	NO
9	List any major capital expenditures planned/requested for the next few years. Have they been budgeted?	?
10	Describe any extremely problematic, historically chronic, or immediate facility needs.	OUTVANDIZO HVAC - RT IN CLASS ROOMS
11	Describe any shared building or site elements or unique arrangements with neighboring properties, entities, or tenants.	SHANE PARK w/ CITY



Mark the column corresponding to the appropriate response. Please provide additional details in the Comments column, or backup documentation for any <b>Yes</b> responses. (NA indicates "Not Applicable", Unk indicates "Unknown")						
QUESTION		RESPONSE				COMMENTS
		Yes	No	Unk	NA	
12	Are there any unusable or "down" areas, units, or spaces within the facility?		X			
13	Is the facility served by a private water well, septic system or other special waste treatment system?		X			
14	Are there any problems with the utilities, such as inadequate pressure or capacities?		X			
15	Have there been any leaks or pressure problems with natural gas service?		✓			
16	Are there any problems with erosion or areas with storm water drainage issues?		X			
17	Are there any problems with the landscape irrigation systems?		X			
18	Are there any problems or inadequacies with exterior lighting?		X			
19	Are there any problems with foundations or structures, like excessive settlement?			X		
20	Are there any known issues with termites or other wood-boring pests?		X			
21	Are there any wall, window, basement or roof leaks?		X			
22	Are there any plumbing leaks or water pressure problems?		X			
23	Are any areas of the facility inadequately heated, cooled or ventilated?		X			
24	Are there any poorly insulated areas?		X			
25	Do any of the HVAC systems use older R-11, 12, or 22 refrigerants?		X			
26	Has any part of the facility ever contained visible suspect mold growth?		X			
27	Have there been indoor air quality or mold related complaints from building occupants?		X			

Mark the column corresponding to the appropriate response. Please provide additional details in the Comments column, or backup documentation for any <b>Yes</b> responses. (NA indicates "Not Applicable", Unk indicates "Unknown")						
QUESTION		RESPONSE				COMMENTS
		Yes	No	Unk	NA	
28	Are there any known unresolved building, fire, or zoning code issues with the governing municipality?		X			
29	Is there any pending litigation concerning the property?		<del>Yes</del>	X		
30	Are there outstanding accessibility issues at the facility? (Go over and fill out first 'History' subsection of separate ADA checklist.)					SCITADVISORY ADA UPDATES SUMMER 2016
31	Are there any EMG 'red flag' issues at the facility? (Go over and fill out attached checklist below.)	X				ATTACHED
32	Are there any other unresolved construction defects or significant issues/hazards at the property that have not yet been identified?		X			



Signature of person interviewed or completing form

5/5/16

Date



## RED FLAG CHECKLIST & MATRIX

Mark the **single** column corresponding to the most appropriate situation. (**PSQ only** indicates POC acknowledged presence during interview but item was not observed on-site; **OBS only** indicates the item was observed but not identified as known to be present during interview process; **PSQ & OBS** indicates item was both verbally identified and physically observed; **NOT EVID** indicates the item was neither observed during limited visual assessment nor identified as present during discussions).

RED FLAG ISSUE		OBSERVED?				GUIDANCE
		PSQ only	OBS only	PSQ & OBS	NOT EVID	most prevalent time of potential use
1	Fire Retardant Plywood (FRT)	X	X	X	X	1955 to 1998; as roof sheathing; view attics; sometimes stamped; moisture absorbance leads to premature failure
2	Engineered / Hardboard Wood Siding		X			any time; Masonite, T-111; water damage and premature failure ON PORTABECOS
3	Exterior Insulation and Finish System (EIFS)				X	any time; water penetration and premature failure (looks like stucco but feels "lighter")
4	Galvanized Water Piping	X	X			prior to early 1980's; common in 1970's; pinhole leaks and interior mineral build-up
5	Polybutylene Water Piping	<del>                </del>	<del>                </del>		X	1977-1995; mostly relevant to housing; grey plastic commonly leaks at joint fittings
6	ABS Piping Recall	<del>                </del>	<del>                </del>		X	1984-1990; faulty resin by 5 manufactures; very difficult to discover & visually observe
7	Cadet/Encore Wall Heater Recall				X	1982-1999; mostly relevant to housing; collect & cross-check model numbers; potential fire hazards
8	PTAC Recall (Goodman/Amana)				X	1996-2003; mostly relevant to housing; faulty thermal override switch; collect & cross-check model numbers
9	Aluminum Wiring (Interior)	<del>                </del>	<del>                </del>			1964-1975; more concerns with interior and smaller gauge
10	Federal Pacific Stab-Lok Electrical Panels				X	prior to 1986; potential fire hazards
11	Fused Electrical Panels				X	prior to early 1960's; easily tampered with, as such potential fire hazard
12	Low Unit Amperage				X	any time; relevant to housing
13	Fire Sprinkler Head Recalls				X	1960-2001; more heavily 1990's; Central, Gem, Star, Globe, Omega can be suspect; collect & cross-check model numbers
14	Dishwasher Recalls				X	1983-1989: GE, Hotpoint 1997-2001: GE, Hotpoint, Maytag, Jenn-Air, Kenmore, Eterna collect & cross-check model numbers; potential fire hazards



## FACILITY CONDITION ASSESSMENT

CIRCLE VIEW ELEMENTARY  
6261 HOOKER DRIVE  
HUNTINGTON BEACH, CALIFORNIA 92647

EMG PROJECT NO: 119317.16R000-001.017

On the day of the site visit, provide EMG's Field Observer access to all of the available documents listed below. Provide copies if possible.

### INFORMATION REQUIRED

- |   |   |
|---|---|
| <ol style="list-style-type: none"><li>1. All available construction documents (blueprints) for the original construction of the building or for any tenant improvement work or other recent construction work.</li><li>2. A site plan, preferably 8 1/2" X 11", which depicts the arrangement of buildings, roads, parking stalls, and other site features.</li><li>3. For commercial properties, provide a tenant list which identifies the names of each tenant, vacant tenant units, the floor area of each tenant space, and the gross and net leasable area of the building(s).</li><li>4. For apartment properties, provide a summary of the apartment unit types and apartment unit type quantities, including the floor area of each apartment unit as measured in square feet.</li><li>5. For hotel or nursing home properties, provide a summary of the room types and room type quantities.</li><li>6. Copies of Certificates of Occupancy, building permits, fire or health department inspection reports, elevator inspection certificates, roof or HVAC warranties, or any other similar, relevant documents.</li><li>7. The names of the local utility companies which serve the property, including the water, sewer, electric, gas, and phone companies.</li></ol> | <ol style="list-style-type: none"><li>8. The company name, phone number, and contact person of all outside vendors who serve the property, such as mechanical contractors, roof contractors, fire sprinkler or fire extinguisher testing contractors, and elevator contractors.</li><li>9. A summary of recent (over the last 5 years) capital improvement work which describes the scope of the work and the estimated cost of the improvements. Executed contracts or proposals for improvements. Historical costs for repairs, improvements, and replacements.</li><li>10. Records of system &amp; material ages (roof, MEP, paving, finishes, furnishings).</li><li>11. Any brochures or marketing information.</li><li>12. Appraisal, either current or previously prepared.</li><li>13. Current occupancy percentage and typical turnover rate records (for commercial and apartment properties).</li><li>14. Previous reports pertaining to the physical condition of property.</li><li>15. ADA survey and status of improvements implemented.</li><li>16. Current / pending litigation related to property condition.</li></ol> |
|---|---|

Your timely compliance with this request is greatly appreciated.